

TOYOTA PRIUS	2009 1.5 HYBRID RATING	2015 1.8 HYBRID RATING	COMMENTS
Battery Location - Removal	3	3	2009 - Right corner of trunk. 2015 - Can't be easier.
Fuel Filter Removal	1	3	2009 - Gas tank assembly required. 2015 - Remove back seat and remove pump.
DLC Location, OBD-II	5	5	2009 - Left below steering wheel.
Fuses/Relays	5	5	2009 - Easy to access. 2015 - Many places.
PCM Location	4	4	2009 - Under dash. 2015 - Under hood.
Spark Plugs	4	4	2015 - Iridium type.
Air Filter	3	4	2009 - Be careful.
PCV Valve	2	3	2009 - EPA requires; hard to access. 2015 - Under a plate under the intake manifold.
Oil Filter, Bolt, Refill	4	3	2009 - Spin-on filter. 2015 - Uses a paper cartridge and O Ring, Use 0/20 oil only.
High Voltage Service Plug	4	5	2009 - Left corner of battery pack. 2015 - Near spare tire looking at you.
A/T Transmission Service	4	4	2015 - Drain and fill only.
Overall Accessibility Under Hood	4	4	2009 - Removing the hood, cowl and wipers helps a lot. 2015 - Preventive maintenance is easy, but other jobs can be difficult.